RADIO SHACK TRS-80

CUSTOMER SERVICE BULLETIN NO. | 1590-04

Description **SuperSCRIPSIT**

Model **III V 01.02.02**

Stock No. **260-1590**

Date **OCT 5, 1984**

*****PURPOSE*****
        Modifications have been developed to reduce the chances
of SuperSCRIPSIT, 26-1590, "locking up" under adverse operating conditions.
Modifications to the program are being accomplished by PATCHING.

*****DISCUSSION*****
        The PATCHES shown below update your software to Ver-
sion 01.02.03. Please log the new version number in your Version Log as soon
as you have applied the PATCHES shown under "PROCEDURE". A brief power outage
or an improper exit from the program can cause a screen to show "garbage" or
to lock up. This happens particularly when block action commands are attempt-
ed. The patches below are to reduce the chance of the situation happening.

*****PROCEDURE*****
        At TRSDOS READY type in the following patches for the pro-
blem.

PATCH SCR16/CTL (ADD=8DE8,FIND=EDB0DD7E00,CHG=CDB07C0000)
PATCH SCRIPSIT/CMD (ADD=7CB0,FIND=0000000000,CHG=E5210000CD)
PATCH SCRIPSIT/CMD (ADD=7CB5,FIND=0000000000,CHG=C165E12802)
PATCH SCRIPSIT/CMD (ADD=7CBA,FIND=0000000000,CHG=EDB0DD7E00)
PATCH SCRIPSIT/CMD (ADD=7CBF,FIND=00,CHG=C9)

To update the version number to 01.02.03, apply the following patch.

PATCH SCR17/CTL (ADD=8EC7,FIND=32,CHG=33)

If you need assistance, please contact your Radio Shack Computer Center,
Radio Shack Computer Marketing Department, or Radio Shack Participating
Dealer.